

OIL COALESCING PLUS

Tectran now offers a line of **OCP™** Model 9 & 1200 air dryers and desiccant cartridges. Our **OCP™** line offers all the same great features and benefits of our standard line with the addition of an oil coalescing filter to provide even greater protection against oil particles entering your air system.



Model 1200 Air Dryer
Part No. AT955205C
Stk. Code 14706



Model 1200P Air Dryer
Part No. AT955300C
Stk. Code 14707



Model 9 Air Dryer Kit
Part No. AT065226K
Stk. Code 14693



Model 1200 Desiccant Cartridge
Part No. AT950068
Stk. Code 14299



Model 9 Desiccant Cartridge
Part No. AT107796C
Stk. Code 14694

| Part No. | Stk. Code | Description | Interchange |
|-----------|-----------|---|----------------------|
| AT065226C | 14692 | OCP™ Model 9 air dryer only - 12 volt | 109685PG |
| AT065226K | 14693 | OCP™ Model 9 air dryer w/brackets - 12 volt | 5009378PG |
| AT107796C | 14694 | OCP™ Model 9 desiccant cartridge | 107794PG 107796PG |
| AT950068 | 14299 | OCP™ Model 1200 desiccant cartridge | R950068 5008414PG |
| AT955205C | 14706 | OCP™ Model 1200 Dryer only - 12 volt | S432 421 040 0 |
| AT955300C | 14707 | OCP™ Model 1200P Dryer only - 12 volt | R955079 |



DID YOU KNOW...

With the new EPA Regulations implemented over the last ten years, truck OEMs have added highly technical systems to reduce nitrogen oxide and particulate matter in emissions. Oil contaminated air negatively impacts these systems, make sure your air system is operating at peak performance with TECTRAN's **OCP™** line of products

For complete Tectran Patent & Trademark information, see www.tectran.com/patents



TECTRAN - USA
2345 Walden Ave., Suite 100
Cheektowaga, NY 14225

Ph: 800.776.5549
Fx: 716.894.9623
E: orders@tectran.com

TECTRAN - CANADA
2400 Anson Drive
Mississauga, ON L5S 1G2

Ph: 905.678.7700
Fx: 905.678.6210
E: customerservice@tectran.com

www.tectran.com

Stock # PB20170315OCP
©2018 Tectran
All Rights Reserved.